

No. EM1 (10)83/16386-99

Dated: 12.11.92

CIRCULAR NO. 368

Sub: Provision of Glass Strip at the edge of depressed portion of floors.-----

C.T.E., during the inspection of one of the works in DDA, had observed that glass strip had been provided at the edge of the depression of floor in the Kitchen. During inspection, this glass strip was found to be breaking away and no useful purpose was, therefore, served by providing the glass strip at the edge of the depressed portion.

It is enjoined upon all field Engineers to ensure that, in future, no glass strip is provided at the edge of depressed portion in the floors. All such edges of the depressed portion of the floors should be finished straight along with the flooring.

*H.D. Sharma*  
(H.D. SHARMA)  
ENGINEER MEMBER

Copy to:-

1. All the Chief Engineers with 25 spare copies for circulation.
2. Chief Engineer (QC), DDA with 10 spare copies for circulation.
3. Chief Engineer (Elect.) with 25 spare copies for circulation.
4. Chief Engineer (Design), DDA with 5 spare copies for circulation.
5. G.M., ISBT, DDA with 5 spare copies for circulation.
6. Director (Hort.) North & South with 10 spare copies circulation.
7. Director (MM) with 5 spare copies for circulation.
8. File No. EM8 (55)88/ CTF/NZ.

*H.D. Sharma*