DELHI DEVELOPMENT AUTHORITY
ENGINEER MEMBER'S OFFICE

NO:EM1(10)83/15977 Dated:5-11-92

INSTRUCTION NO. 365

C.T.E.'s organisation, during inspection of one of the works in DDA, had observed certain deficiencies on the basis of their random check. The CTE had desired that a detailed check of the entire work should be conducted to identify similar deficiencies in the rest of the work and, thereafter, a report should be sent to them.

However, the field staff did not comply with the observations of the CTE for as long as 4 to 5 years, during which time, the houses were allotted and the possessions were also taken over by the allottees. After all these developments, a report was sent to the CTE that no detailed checking was possible at such belated stage and that only a random check had been conducted, which had been found to be satisfactory.

Such an approach on the part of the field staff reflects their careless and indifferent attitude towards their duties and the CTE's paras.

It should be clearly understood by the field staff that any checking done by CTE/CE(QC) is just a random checking and their observations are only indicative, after which the field staff must invariably check the entire work in detail for as-certaining the total extent of the deficiencies pointed out by these inspecting agencies for initiating suitable remedial action. More so, when specifically asked to do so by the CTE/CE(QC).

Any failure to comply with these instructions shall make the concerned field staff liable for disciplinary action.

(H.D. SHARMA)
ENGINEER MEMBER

1. All C.Es, DDA.
2. All S.Es, DDA.
3. All E.Es, DDA.

Copy to:-
1. CTE for information in continuation of CE(R)'s letter No.CE(R)4(6)90/CE(QC)/1145 dated 19/20.5.92.
2. C.E.(QC) for information.