


196
19
DELHI DEVELOPMENT AUTHORITY

No. 171(10)83/12709

Dt., the

Circular No 119
October, 1985.
1-11-85

It has been reported by the Chief Engineer(LP) that some major clearance operations were carried out by the Land Protection Cell during the last two months and the lands were cleared of encroachments. CEs and Director(Hort) were required to protect the land by fencing/construction of boundary walls and by taking up the development works as per the plan/^{DCD}land use immediately after the clearance operations but proper action in this regard has not been taken in many cases. Chief Engineer(LP) has also reported that in some cases re-encroachments of land have also taken place. In case immediate action is not taken by the Zonal Chief Engineers and Director(Hort) for protecting land by way of providing fencing/compound wall and taking up development works, the land retrieved from the land grabbers and unauthorised squatters are likely to be lost again. It is therefore, enjoined upon all CEs and Director(Hort) that after the encroachments have been removed by the Chief Engineer(LP) and handed over to Chief Engineers/Director(Hort), they should take immediate action for construction of compound wall so that the land is properly demarcated and also protected from re-encroachment. The development works in this area should also be undertaken immediately in consultation with CA/Director(CP). The cost of providing boundary wall shall be chargeable to the development scheme of the area.


(J.K. Varshneya)
Engineer Member.

Copy to:-

1. All CEs except CE(D) & (QC).
2. All SEs.
3. Director(Hort).
4. All EEs.
5. All Deputy Directors(Hort).

Copy also to VC, DDA for information.