

236

144

DELHI DEVELOPMENT AUTHORITY


No. Em 1(10)83/4770 Dt., the 15th April, 1986.

Circular No 144

During his various inspections, the Lt. Governor has found that the drains in the housing colonies have been designed in the most purfunctory manner without any thought for the levels, gradients and the ultimate outfall with the result that in most of the drains, water flows in the reverse direction and there is no ultimate outlet for water. To put an end to this unsatisfactory state of affairs, it is hereby ordered that:-

(a) In all new housing pockets which are being constructed now, a proper drainage plan will be made showing the levels of the various drains which are to be constructed to ensure that proper gradients and ultimate outfall is available for drainage scheme. In all such cases, the Superintending Engineer will accord his approval by signing on such drainage plan. The concerned Chief Engineer will exercise test checks during their inspections to ensure that the whole drainage scheme is a workable entity.

(b) In the case of existing housing pockets and colonies (not yet transferred to MCD and which are under the maintenance of DDA) drainage plan showing the existing levels will be prepared and modification schemes to make the whole scheme functional will also be prepared and the likely expenditure for correcting the drainage schemes will be worked out and consolidated scheme will be put up to the undersigned for his approval.

  
( J.K. Varshneya )  
Engineer Member

All CEs/SEs/EEs/AEs

Copy to L.G. Inspection file.