NO.EM.1(10)83/3460

Dt: 20&21st June, 1983

CIRCULAR NO. 26

Sub:- Vaish committee report.

Three interim reports of the Vaish Committee have already been circulated to All CE/ACEs/SEs for their information and urgent necessary action with regard to:-

- Rectification of defects wherever these have occurred; particularly in the substandard houses which have been brought out in the report; and -
- ii. Execution of all further works in accordance with the proper quality practice and specifications.
- 2. All concerned CE/ACEs/SEs/EEs have already been advised to take up the works of rectification and strengthening on priority basis. It has been emph-sised during my inspection, personal discussions, and otherwise that they should take all actions which are necessary to ensure that the defective and sub-standard work is rectified properly and urgently. They have also been requested to ensure that every thing possible is done most urgently to prevent any further accidents in the case of houses already constructed by taking steps to properly strengthen and specify the defective area of construction etc.etc.
- 3. These instructions are being reiterated to bring the aforesaid matter to the pointed notice of all concerned for strict compliance and check up.

Sd/-(K.D. BALI) ENGINEER MEMBER