NO:

Dt: 10.9.91

EM. 1(10)83/1:686,

STANDING INSTRUCTION NO. 338

Sub: Approval of report of Soil Consultant/Structural Consultant/Architectural Consultant.

It has been observed that several reports, which are being received from soil consultants/structural consultants/ architectural consultants on various projects/works are not being approved/signed by the Authority competent to accord technical sanction to the estimates and the same are being used/adopted in works without any proper approval/signatures of the competent authority.

Similarly, several architectural drawings issued by the provate consultants are not being signed for several months by concerned Chief Architect/Addl.Chief Architect/Senior Architect and are being issued without signatures to the Engineering Department which result in processing of project estimates, accord of technical sanction and execution of the projects inordinately.

All concerned engineers are directed to accord approval to the reports of the soil consultants/structural consultants and also sign the designs and drawings including reports before execution and adoption of the same in the projects/works. Similarly all Planners/Architects/ Chief Architect/Addl.C.A./

6r.Architects are directed to ensure approval in writing of all drawings and reports submitted by the private architectural consultants.

This issues with the approval of Engineer Member, DDA.

(R.G. Bhatnagar) Director(Works) DDA.

- All concerned for information and strict compliance.
- 2. C.E.(QC) w.r.t. his letter dated 26.6.91

DELHI DEVELOPMENT AUTHORITY

NO: EM (10) 83/1 4336

dt.25.10.91

CORRIGENDUM TO STANDING INSTRUCTION No. 338

SUB: Approval of report of Seil Consultant, Structural Consultant/ Architectural Consultant.

Standing Instruction No. 338 regarding the cited subject/vide
No. EMT(10) 83/11686 dated 10.9.91.

The fifth line of pare-2 of the said Standing Instructions shall be read as under:-

" ... Engineering Department which result in delay in processing of project estimate ... " instead of

"... Engineering Department which result in processing of project estimates..."

Director(Works)

Copy to:-

- 1. All Chief Engineers with 25 spare copies for circulation among
- 2. Chief Engineer (Q.C.) DDA
- 3. All Planners/Architects/Chief Architect/Addl. C.A./Sr. Architects
- 4. G.M. I.S.B.T. with 5 span conies for circulation.
- 5. Director (Hort.) North & South DDA.

E.O.-I to E.M. D.D.A./