

C I R C U L A R NO: 376

SUBJECT : C.C. GOLA ON TERRACE TO BE PROVIDED AFTER CUTTING CHASE IN BRICK WORK OF PARAPET WALL.


\*\*\*\*\*

The CTE, during inspection of one of the works in DDA, had observed that the chase in the brick work of terrace wall had not been cut before providing C.C. gola, as required under para 12.17.2 of CPWD specifications 1977 Vol.II. Subsequently, only a reduction was effected for not cutting the chase in the parapet wall for providing C.C. Gola.

The provision of C.C. Gola after cutting a chase in the brick work of the parapet wall is required to serve a definite purpose of checking any leakage at the joints of parapet wall and terrace and merely effecting reduction in rates on account of the same does not serve the required technical purpose.

It is therefore, enjoined upon all the field engineers to ensure that a proper chase is cut in the brick work of the terrace wall as per the above mentioned provisions of C.P.W.D. specifications before providing C.C. gola on the terrace.

Any lapse in this regard on the part of the supervisory staff shall be viewed seriously.

  
( H.D. SHARMA )  
ENGINEER MEMBER

All Chief Engineers

All Suptd. Engineers


All Executive Engineers

Director(Hort.) North & South

G.M., I.S.B.T.

Concerned file No.EM8(97)88/CTE/WZ

Copy to:- Vice-Chairman, DDA, for information.

  
( S.M. MADAN )