

NO:EM1(10)83/9007

Dated:-21/6/93

CIRCULAR No. 400


SUB: Poor test results of samples collected by Q.C. Wing during their inspections.

--- --

It has been reported by the C.E.(QC) that the percentage of failure of samples collected by the officers of the Q.C. Wing during their inspections in the last three years had been more than 50%, which, off late, has increased to an alarming 75% during the first quarter of the current year. Such a high percentage of failure of test samples is a matter of grave concern and V.C., DDA has taken a serious note of the same. Needless to point out that such a high percentage of failure of samples is a very sad reflection of the inadequate/ineffective supervisory control being exercised by the field staff during the execution of the works. This trend definitely needs to be reversed, as the department just can not afford to allow the continuance of such a state of affairs.

It is, therefore, enjoined upon all field engineers to ensure that the entire quantity of the materials, brought to site by the contractors, strictly conforms to the specifications. There should be no reason of the failure of any sample collected from the materials which have been brought to the site and are being used in the work. In future, strict action shall be taken against the defaulting JEs/AEs/EEs, in case, high percentage of failure of samples collected from the work sites under their control is detected. This note of caution may please be noted carefully by all concerned.


These instructions must be scrupulously followed.


(H.D. SHARMA)
ENGINEER MEMBER

1. All C.Es, DDA i/c CE(Elect.) and CE(QC).
2. All S.Es, DDA i/c SE(QC).
3. Director(Monitoring)
4. Director(Hort.) South and North.
5. All EEs, DDA i/c EE(QC) and EE(Elect.)
6. All Dy. Directors(Hort.)DDA.
7. File No.PA/Secy./DDA/Misc./93.

Copy to:-

V.C., DDA for kind information.


ENGINEER MEMBER