

## DELHI DEVELOPMENT AUTHORITY

No.EM.1(10)83/3363

Dated: 10&amp;11.4.85

## CIRCULAR NO. 92

On some of my inspections I have noticed that adequate care is not taken in making proper centering and shuttering as per standard specifications. In most of the cases, cross-bracings are missing, shuttering for chhajja is supported on the chhajja of lower floor without any support from below which is against the rules. It is also seen that the supervisory staff does not point out the mistake to the junior staff. Please ensure that centering and shuttering is done properly and as per standard specifications.

All Officers to note for strict compliance.

Sd/-  
(J.K.VARSHNEYA)  
ENGINEER MEMBER

1. All AEs
2. All EEs
3. All SEs
4. All CEs.