

MOST IMMEDIATE

DEBIT DEVELOPMENT AUTHORITY U.C.L.P. No 192

No: Am 1(10)83/2637

Date: 24/2/87

I have observed that instructions are not followed by the field staff after inspection by the senior officers. There should be site order book at each place of work where the value of the contract is more than Rs. 4 lacs. Whenever, the Ex. Engineers inspect the work, they should record their inspections of important nature in this register itself. Their inspection notes may follow separately. SEs & Executive Engineers should please follow these instructions with immediate effect.

V.S. Murti
(V.S. Murti)
Engineer Member
18.2.87.

Chief Engineer (EZ)
Chief Engineer (WZ)
Chief Engineer (NZ)
Chief Engineer (SZ)
Chief Engineer (MZ)
Chief Engineer (Bohini)

with 20 more copies for
circulation to SEs/EEs.