

## DELHI DEVELOPMENT AUTHORITY

No. EMI (10)83/148

Dated: 3.1.86

## CIRCULAR NO. 126

The Asstt. Engineers/Executive Engineers are required to test check the measurements for works in the manner specified in Section 7 of CPWD Manual Vol. II. The non-observance of this codel formality not only attracts audit objections but causes delay in finalisation of bills. In certain cases if test check of measurements is not done timely, it cannot be done later owing to the works having been covered up. It is, therefore, enjoined upon all EEs/AEs to follow these instructions contained in the Manual regarding test check of measurements very strictly.

The concerned SEs/EEs should ensure that before relieving ant EE/AE under their control on transfer/repatriation etc. The requisite amount of test check of works executed during their tonure has been conducted and completion certificate in respect of completed works have recorded by them.

Sd/-  
(J.K.VARSHNEYA)  
ENGINEER MEMBER

All CEs/SEs/EEs