NO: EM:1(10) \$ 4/ Vol. I /14646

Dated:-15-11-94

0

*STANDING INSTRUCTION NO. 637

while reviewing the progress of Horticulture works on 28-10-94, following directions were issued by the Vice-Chairman for taking further action by the concerned:

- At the time of preparing the landscape of any 1. green area, Director(Landscape) would keep in mind that all the structures, may it be a Chowkidar's hut or pump house or site office, get merged with the landscape of the area.
- There should be no ugly looking Chowkider's 2. hut or pump house or any other structure existing in the park. Wherever such structures are already existing, Horticulture Wing would provide creepers in consultation with Director (Landscape) so that the structures get merged with the landscape of the area.
- To ensure that garden/park is clearly visible 3. to the people walking on the road, no boundary wall or fencing of park in any of the horticulture greens would be raised. In case, it is felt that the boundary wall of any park is required to be raised, then that would be with the prior approval of Engineer Member.

This issues with the approval of Engineer Member.

ALL CHIEF ELGINEERS WY

CHIEF ARCHITECT

DIRECTORS (HORT.) -NORTH & SOUTH

DIRECTOR (LANDSCAPE)

nicopy to:-

Vice-Chairman for his kind information. In file No.EM. 3(64)88/Hort./Genlewith E.O. III.

dito CE CUS.

DIRECTOR (WORKS

DIRECTOR (WORKS)

No CE (WE) 12(44) 94 An sen ile

T.0 15 6014

UIN