

DELHI DEVELOPMENT AUTHORITY

No. EM.1(10)83/6388

Dated: 1.9.84

CIRCULAR NO. 62

As per CPWD Code, Superintending Engineers are requested to inspect the divisional offices under their charge atleast once a year and record of the result of such inspections is required to be maintained in the prescribed performa. It has, however, come to my notice that the inspection of divisional offices under the charge of SE is not being carried out regularly. Some of the divisionals have not been inspected by the SEs during the last 3-4 years. This has been viewed with concern. All SEs are requested to inspect the divisional offices under their charge and report of the inspection should be submitted in the prescribed form PWD-29 within a period of 2 months. SEs are also requested to initiate prompt action on irregularities found out during the inspection.

Sd/-
(J.K. VARSHNEYA)
ENGINEER MEMBER.

All CEs

All SEs