

DELHI DEVELOPMENT AUTHORITY  
ENGINEER MEMBER'S OFFICE

NO:EM(10)83/7654-58

dt. 2.5.90

C I R C U L A R No. 293

Subj- Regarding Kota stone work and brick work.

During inspection of various sites, it has come to the notice of undersigned that quality of Kota stone work being executed is not up to the requisite standard.

Also it has been observed that the bricks stacked at site for brick work were of very poor quality. In this context attention of all field Engineers is drawn to the specifications relating to Kota stone and brick works which should meticulously be followed by all Engineers.

*V.S. Murti*  
24/4.90  
( V.S. Murti )  
Engineer Member

*D.K. ...*  
23.4.90

Copy to:-

1. All Zonal Chief Engineer with 25 spare copies for circulation.
2. C.E.(Q.C.) with 10 spare copies.
3. G.M., I.S.B.T. with 5 spare copies.
4. Director(Hort.) North & South with 10 spare copies.
5. All E.Os & A.Es, E.M. office.

*B. ...*  
E.O.-I to E.M.  
D.O.A.