Carl Daring 11)


DELHI DEVELOPMENT AUTHORITY OFFICE OF SUPERINTENDING ENGINEER (HQ)

No. SE(HQ)/EZ/2007/CR/ 4287

dt: 23.5.08

To

The Secretary, CRB, DDA, Vikas Minar, ITO, New Delhi-110002.



Sub: Inspection of works executed by M/s Lakshmi Constructions who has applied for enlistment as Class-I (B&R) in DDA.

Ref: Your letter No: F 4(8)80/10/2007/I(8&R)/Secy/ 261 dt: 12.5.08.

With reference to your letter cited above vide which the undersigned has been asked to inspect the following three works and submit the report to Secy./CRB:

Name of work	Executed_under
C/o Software Factory, C-7,	Lakshmi Paints & Chemicals,
Sec-3, Noida.	C-7, Sec-3, Noida.
Gross Amount: Rs.2,63,45,000/-	
C/o Prayer Hal' (Sai Niketan) at	Chairman, Sai Probodhini,
Plot No.5, Jasola Vihar, DDA.	G-78, Jasola Vihar, Sec-8,
Gross Amount: Rs.72,25,000/-	New Delhi-110025.
C/o Extn. to Navin Upchaar	Director, Navin Upchar
Hospital, 365, Sec-19, Noida.	Sadan Pvt. Ltd.
Gross Amount: Rs.1,80,00,000/-	A-364, Sec-19, Noida (UP).
	C/o Software Factory, C-7, Sec-3, Noida. Gross Amount: Rs.2,63,45,000/- C/o Prayer Hall (Sai Niketan) at Plot No.5, Jasola Vihar, DDA. Gross Amount: Rs.72,25,000/- C/o Extn. to Navin Upchaar Hospital, 365, Sec-19, Noida.

The above three works executed by M/s Lakshmi Constructions have been inspected by the undersigned on dt:19.5.08 and found satisfactory in respect of quality, technical capability, financial status, time & labour management.

(Er. V.S. Jainth) 23/5/09

SE(HQ)/EZ

DELHI DEVELOPMENT AUTHORITY SUPDTG. ENGINEER/CC-III

No. FI(44) 2005 | SET(CC-3) 1215 DT: 23/5) 2000

To

The Secretary

Contractor's Registration Board

Ist floor, Vikas Minar

New Delhi

23-5-08


Sub: Inspection of works executed by M/S Lakshmi Constructions who has applied for enlistment as Class-I(B&R) in DDA.

Please refer your office letter no.F4(8)80/10/2007/1(B&R)/Secy-261 dt. 12.05.08 on the above cited subject. The undersigned have inspected the following stated works on 19.05.08 and the assessment of quality has been mentioned in the remarks column against each work:

SL. NO.	NAMES OF WORK	REMARKS
Ι.	C/o Extn. to Navin Upchaar Hospital, 365, Sector-19, NOIDA	The building is extension to Navin Upchaar Hospital. It is R.C.C. framed structure consist of ground floor + Two storey and part basement. The building is finished with glass façade in the front portion and glass with brick tiles in the side.
		Vitrified tiles were used and green marbles with white marble Strips were used in the lobby. The line and levels are found satisfactory. The lines and levels of the walls also truly in plumb line. The building is

		approximately 15-mt. high. The gross amount of the building is approximately 1.80-crores. The overall quality of the work is satisfactory and can be graded as Very good.
2.	C/O Prayer Hall(Sai Niketan)at plot no.5, Jasola Vihar, DDA.	The gross amount of the building is Rs. 72,25,000/ This building is constructed as R.C.C. framed structure. At ground floor level, prayer hall of size 28'x70' has been constructed and at first floor level, it is being used as residential purpose. The general span of the Hall is 5-mt.x9-mt. The building has ground floor and first floor excluding basement of size 24'x14'. The building is grit wash finished from outer side. Marble tiles have been used in the Prayer Hall flooring. The quality of work found satisfactory and can be graded as V.Good.
3.	C/o Software factory, C-7, Sector-3, NOIDA Gross amount: Rs.2,63,45,000/-	This building has also RCC framed structure. The building size is 50-mt.x100-mt.(approx.). The general span is 5-mt.x13-mt. And there is ground floor + three storied excluding basement. The outer finish is aluminum glass facade. The vitrified tiles have been used in the flooring inside. Udaipur green marble used in stair case, lobby and Kota stone in open area in ground floor has been provided. On the terrace

structural steel with G.I.
Shuttering and Koba treatment
on terrace roof.
The general quality of work was
found to be satisfactory and can
be graded as V.Good



S.E./CC-3/DDA


DELHI DEVELOPMENT AUTHORITY OFFICE OF THE SUPTOG. ENGINEER/CC-14/DDA

No: 1-10(25) of con 4 DIDA

Dated: 19157 &

To.

The Secretary, Contractor's Registration Board Ist Floor, Vikas Minar, NEW DELHI.



SUB: INSPECTION OF WORKS EXECUTED BY M/S. LAKSHMI CONSTRUCTIONS WHO HAS APPLIED FOR ENLISTMENT AS CLASS-I (B&R) IN DDA.

Please refer 10 your office letter F.4(8)80/10/2007/1/B&R/Secy./261 dated 12.05.2008 on the above subject matter. I have inspected the following stated works on dated 17.05.08 and the assessment of quality has been mentioned in the remarks column against each work.

NO. NAMES OF WORK REMARKS

C/o. Software factory, i.

C-7, Sector-3, Noida.

It is completed work, It is R.C.C. framed structure on building size of

50 mtr.x 100 mtr.(approx.).

General span:

5.00 m x 13.0 m

No. of storeys:

Ground + three storeys

excluding basement.

Outer finish:

Alluminium Glass facade.

Flooring inside: Stair case risers/treads:

Vitrified tiles.

Green marble.

Terrace roof Shuttering:

Structural steel with G.I. Shuttering and coba treatment on terrace roof.

The general quality of work was found to be quite satisfactory and can

be graded as good.

 C/o. Prayer Hall (sai Niketan) at plot No.5 Jasola Vihar, DDA.

> General span: No. of storeys:

Outer finish: Prayer hall flooring:

 C/o. Extn. to Navin Upchaar Hospital,365 Sector,19, Noida.

External Finish:

The building is constructed as R.C.C. framed structure. At Ground floor level, prayer hall of size 28'x70' has been constructed and at first floor level, it is used for residential purpose.

5.00m x 9.00m Ground + first floor excluding basement of size 24'x14'. Grit wash. Marble tiles.

The additional facilities like class rooms, liberary etc. have also been provided in plot area.

The quality of work found satisfactory and can be graded as good.

The building is extension to Navin Upchaar Hospital. It is R.C.C. framed structure consist of ground floor + Two storeys and part basement.

Front - Glass Facade.

Hospital side - Glass with brick tiles.

Flooring in rooms: Lobby:

Vitrified tiles.
Green marble with while marble strips.

The quality of work found satisfactory and can be graded as good.

(J.S. ASNANI)
SUPTDG. ENGINEER/CC-14/DDA