

214

ANNEXURE VII
PERFORMANCE REPORT OF WORKS

PART I

(To be filled in by the contractor in duplicate in respect of each work cost of which falls within the range prescribed for eligibility as per para 19 of enlistment read with Table -I. One copy be submitted to Reporting Officer and other, containing acknowledgement of receipt and seal of office of reporting officer, be submitted to Secretary (CRB))

1. Period:
2. Name & Address of contractor: *M/s Hoshiyar Singh, village Rangpuri PO Gurgaon Road N.D-37-*
3. Class, Category and Enlistment No.: *Class III, B & R F4(8) 2 misc. Pt IV/III Secy / CRB/R/743*
4. Name & address of enlisting authority: *CRB, Vikas Nagar*
5. Name of Work: *m/o Scheme under N-AII / SEZ (Now SZ) SH: Repair & raising*
6. Agreement No.: *boundary wall in green / ridge area at Adphladrpur Ph II*
7. Name & Address of Division: *GS/EE/Secy 5/ADA/09-10
S.W-D 5 / Sarita Vihar New Delhi-110076*

Sl.	Item	
8.1	Estimated Cost/Tender amount	<i>36,27,387/- 30,01,270/-</i>
8.2	Stipulated date of Commencement & Completion	<i>6-2-10 / 5-8-10</i>
8.3	Percentage progress with date/actual date of completion	<i>30-11-2010</i>
8.4	Gross amount of final bill/work done	<i>28,03,089/-</i>
8.5	Amount of compensation levied, if any	<i>-N.A-</i>
8.6	Amount of reduced rate items, if any	<i>-N.A-</i>
8.7	Did the contractor go for arbitration?	<i>-N.A-</i>
8.8	If yes, total amount claimed and amount awarded	<i>-N.A-</i>


Signature of the contractor

PART II

(To be filled by the department)

9.0 Certified that details given by the contractor in Part - I have been verified and found to be correct/have been corrected wherever necessary.

Delay is partly /not/ fully attributable to contractor.


Signature of Divisional/Sub Divisional Engineer

10.0 Note : After submission of Annexure VII by contractor, reporting officer shall write the Report and forward to Reviewing officer within a week's time. Reviewing officer shall then forward the report to the Enlisting authority within a week's time.

Class	I	II	III	IV	V
Reporting Officer	E.E	E.E	EE	AE	AE
Reviewing Officer	S.E	S.E	SE	EE	EE

Note: The Performance Report shall be countersigned by the respective Chief Engineer also, if the cost of the Work exceeds Rs. One Crore.

2/8

ANNEXURE VII
PERFORMANCE REPORT OF WORKS

PART I

(To be filled in by the contractor in duplicate in respect of each work cost of which falls within the range prescribed for eligibility as per para 19 of enlistment read with Table -I. One copy be submitted to Reporting Officer and other, containing acknowledgement of receipt and seal of office of reporting officer, be submitted to Secretary (CRB))

1. Period:
2. Name & Address of contractor: *M/S Hoshiyar Singh, village Rangpur, P.O Mahipalpur N.D 37 Gurgaon Road*
3. Class, Category and Enlistment No.: *Class III, B&R F4(8)72/m'sc 1A/IV/11/Secy/CRB/R/743*
4. Name & address of enlisting authority: *CRB, Vikas Minar*
5. Name of Work: *m/o Completed Scheme of Nazul Account II under SWZ. SH: C/O 18m wide road in front of H.B.S Hospital in Sec A Part I, Vasant Kunj.*
6. Agreement No.: *20/EE/ISWD/ID-D-A/2007-08*
7. Name & Address of Division: *SWD I, Vasant Kunj New Delhi-110070.*

Sl.	Item		
8.1	Estimated Cost/Tender amount	<i>9,88,865/-</i>	<i>10,72,720/-</i>
8.2	Stipulated date of Commencement & Completion		<i>8-2-08/7-5-08</i>
8.3	Percentage progress with date/actual date of completion		<i>18-11-08</i>
8.4	Gross amount of final bill/work done		<i>15,25,987/-</i>
8.5	Amount of compensation levied, if any		<i>N-A</i>
8.6	Amount of reduced rate items, if any		<i>N-A</i>
8.7	Did the contractor go for arbitration ?		<i>N-A</i>
8.8	If yes, total amount claimed and amount awarded		<i>N-A</i>

[Signature]
Signature of the contractor

PART II

(To be filled by the department)

9.0 Certified that details given by the contractor in Part - I have been verified and found to be correct/have been corrected wherever necessary.

Delay is partly /not/ fully attributable to contractor.

[Signature]
Signature of Divisional/Sub Divisional Engineer

10.0 Note : After submission of Annexure VII by contractor, reporting officer shall write the Report and forward to Reviewing officer within a week's time. Reviewing officer shall then forward the report to the Enlisting authority within a week's time.

Class	I	II	III	IV	V
Reporting Officer	E.E	E.E	EE	AE	AE
Reviewing Officer	S.E	S.E	SE	EE	EE

Note: The Performance Report shall be countersigned by the respective Chief Engineer also, if the cost of the Work exceeds Rs. One Crore.

23

ANNEXURE VII

Part - III

(Serial 1 to 7 are repeat information for proper linkage)

- 1. Period:
- 2. Name & Address of contractor: *M/s Hashiyar Singh, Village Rangpuri Po Gurugram Road N-D 37.*
- 3. Class, Category and Enlistment No.: *Class III, B & R F4(8)72 misc Pt IV/1111/Secy/CRB/A/748*
- 4. Name & address of enlisting authority: *CRB, Vikas Miran*
- 5. Name of Work: *M/o Scheme under N.A.T. (SEZ/Now 52) SH: Repair & raising of boundary*
- 6. Agreement No.: *Wall on green bridge area at Pulpahadpur Ph II*
- 7. Name & Address of Division: *65/EE/SWD 5/ DDA /09-10.*

SWD 5/Sarita Vihar, New Delhi - 110076.

11.1	Quality of work	Outstanding/Very good/Good/ Satisfactory /Poor
11.2	Comments on capability of contractor	
11.2.1	Technical proficiency	Outstanding/Very good/Good/Satisfactory /Poor
11.2.2	Financial soundness	Outstanding/Very good/Good/Satisfactory /Poor
11.2.3	Mobilizations of adequate T&P	Outstanding/Very good/Good/Satisfactory /Poor
11.2.4	Mobilizations of man power	Outstanding/Very good/Good/Satisfactory/ Poor
11.2.5	General behavior	Outstanding/Very good/Good/Satisfactory /Poor

Reporting Officer (Designation and Address)

Executive Engineer
South Western Division-5
Delhi Development Authority

12.1	Quality of work	Outstanding/Very good/Good/Satisfactory/Poor
12.2	Comments on capability of contractor	
12.2.1	Technical proficiency	Outstanding/Very good/Good/Satisfactory/Poor
12.2.2	Financial soundness	Outstanding/Very good/Good/Satisfactory/Poor
12.2.3	Mobilizations of adequate T&P	Outstanding/Very good/Good/Satisfactory/Poor
12.2.4	Mobilizations of man power	Outstanding/Very good/Good/Satisfactory/Poor
12.2.5	General behaviour	Outstanding/Very good/Good/Satisfactory/Poor

Reviewing Officer (Designation & Address)

251

ANNEXURE VII

Part - III

(Serial 1 to 7 are repeat information for proper linkage)

- 1. Period:
- 2. Name & Address of contractor: *M/s Hoshiyar Singh, village Rangpuri, P.O. Mahipalpur N.D-37, Gurgaon Road.*
- 3. Class, Category and Enlistment No.: *Class III, BLR F4 (8) 72 (m/s) 141111/SEYICRBR743*
- 4. Name & address of enlisting authority: *CRB, Vikas Nagar*
- 5. Name of Work: *m/o Completed scheme of Narsul Account-II under SW2-SH! c/o 18m wide road in front of ILBS Hospital in sec-A Pkt. I Vasant Kunj.*
- 6. Agreement No.: *20/EE/ISWD/1/ADA/2007-08*
- 7. Name & Address of Division: *SWD I, Vasant Kunj, New Delhi*

11.1	Quality of work	Outstanding/Very good/Good/ Satisfactory /Poor
11.2	Comments on capability of contractor	
11.2.1	Technical proficiency	Outstanding/Very good/Good/Satisfactory /Poor
11.2.2	Financial soundness	Outstanding/Very good/Good/Satisfactory /Poor
11.2.3	Mobilizations of adequate T&P	Outstanding/Very good/Good/Satisfactory /Poor
11.2.4	Mobilizations of man power	Outstanding/Very good/Good/Satisfactory/ Poor
11.2.5	General behavior	Outstanding/Very good/Good/Satisfactory /Poor

Reporting Officer (Designation and Address)

[Signature]
 Executive Engineer
 South Western Division No.1
 D.D.A., Vasant Kunj,
 New Delhi

12.1	Quality of work	Outstanding/Very good/Good/Satisfactory/Poor
12.2	Comments on capability of contractor	
12.2.1	Technical proficiency	Outstanding/Very good/Good/Satisfactory/Poor
12.2.2	Financial soundness	Outstanding/Very good/Good/Satisfactory/Poor
12.2.3	Mobilizations of adequate T&P	Outstanding/Very good/Good/Satisfactory/Poor
12.2.4	Mobilizations of man power	Outstanding/Very good/Good/Satisfactory/Poor
12.2.5	General behaviour	Outstanding/Very good/Good/Satisfactory/Poor

Reviewing Officer (Designation & Address)

[Signature]