

ANNEXURE VII
PERFORMANCE REPORT OF WORKS

PART I

(To be filled in by the contractor in duplicate in respect of each work cost of which falls within the range prescribed for eligibility as per para 19 of enlistment read with Table -I. One copy be submitted to Reporting Officer and other, containing acknowledgement of receipt and seal of office of reporting officer, be submitted to Secretary (CRB))

- 1. Period:
- 2. Name & Address of contractor: RENU AGGARWAL A-2/1st JANAK PURI ND-58
- 3. Class, Category and Enlistment No.: IV, B & R F4(8)71/06/2007/D/B&R/Reg
- 4. Name & address of enlisting authority: DDA, CRB, 1st FLOOR, VIKAS MINAR
- 5. Name of Work: M/o completed scheme under NDA II SWZ, Renovation of existing stone masonry Bungalow at PVC Bazar, Tikri Kalan.
- 6. Agreement No.: 35/EE/WD2/DDA/10-11
- 7. Name & Address of Division: EE/WD2/B2B, JANAK PURI

Sl.	Item	
8.1	Estimated Cost/Tender amount	1181124/- 1855305/-
8.2	Stipulated date of Commencement & Completion	19-9-10 to 2-11-10
8.3	Percentage progress with date/actual date of completion	21-10-10
8.4	Gross amount of final bill/work done	2151578/-
8.5	Amount of compensation levied, if any	NO
8.6	Amount of reduced rate items, if any	NO
8.7	Did the contractor go for arbitration?	NO
8.8	If yes, total amount claimed and amount awarded	-NA-

Renu
Signature of the contractor

PART II

(To be filled by the department)

9.0 Certified that details given by the contractor in Part - I have been verified and found to be correct/have been corrected wherever necessary.

Delay is partly /not/ fully attributable to contractor.

Sen 6/17
Signature of Divisional/Sub Divisional Engineer

10.0 Note : After submission of Annexure VII by contractor, reporting officer shall write the Report and forward to Reviewing officer within a week's time. Reviewing officer shall then forward the report to the Enlisting authority within a week's time.

Class	I	II	III	IV ✓	V
Reporting Officer	E.E	E.E	EE	AE	AE
Reviewing Officer	S.E	S.E	SE	EE	EE

Note: The Performance Report shall be countersigned by the respective Chief Engineer also, if the cost of the Work exceeds Rs. One Crore.

ANNEXURE VII
Part - III

(Serial 1 to 7 are repeat information for proper linkage)

- 1. Period:
- 2. Name & Address of contractor: RENU AGGARWAL, A-2185 JANAK PURI, ND58
- 3. Class, Category and Enlistment No.: IV, BDR, FU(8) 71/06/2007/IV(BDR)/SECY
- 4. Name & address of enlisting authority: CRB, DDA, 1ST FLOOR, VIKAS MINAR, Scheme 2, WZ-24 - Penovation of water- supply of P.C. ward-
- 5. Name of Work: M/V unexpected
- 6. Agreement No.: 35/EE/WD2/DDA/10-11
- 7. Name & Address of Division: EE/WD2/DDA/B2B Janak puri, ND58

11.1	Quality of work	Outstanding/Very good/Good/ Satisfactory /Poor
11.2	Comments on capability of contractor	✓
11.2.1	Technical proficiency	Outstanding/Very good/Good/Satisfactory /Poor
11.2.2	Financial soundness	Outstanding/Very good/Good/Satisfactory /Poor
11.2.3	Mobilizations of adequate T&P	Outstanding/Very good/Good/Satisfactory /Poor
11.2.4	Mobilizations of man power	Outstanding/Very good/Good/Satisfactory/ Poor
11.2.5	General behavior	Outstanding/Very good/Good/Satisfactory /Poor

Reporting Officer (Designation and Address) *[Signature]* 21/6/12
ASST. ENGINEER-IV
W.D.-2, D.D.A.,
JANAK PURI

12.1	Quality of work	Outstanding/Very good/Good/Satisfactory/Poor
12.2	Comments on capability of contractor	✓
12.2.1	Technical proficiency	Outstanding/Very good/Good/Satisfactory/Poor
12.2.2	Financial soundness	Outstanding/Very good/Good/Satisfactory/Poor
12.2.3	Mobilizations of adequate T&P	Outstanding/Very good/Good/Satisfactory/Poor
12.2.4	Mobilizations of man power	Outstanding/Very good/Good/Satisfactory/Poor
12.2.5	General behaviour	Outstanding/Very good/Good/Satisfactory/Poor

Reviewing Officer (Designation & Address) *[Signature]* 21/6/12
EE/WD-2
DDA

**ANNEXURE VII
PERFORMANCE REPORT OF WORKS**

PART I

(To be filled in by the contractor in duplicate in respect of each work cost of which falls within the range prescribed for eligibility as per para 19 of enlistment read with Table -I. One copy be submitted to Reporting Officer and other, containing acknowledgement of receipt and seal of office of reporting officer, be submitted to Secretary (CRB))

1. Period:
2. Name & Address of contractor: **RENU AGGARWAL A-2/15 JANAK PURI ND-58**
3. Class, Category and Enlistment No.: **IV, B & R, FU(8) 11/06/2007/IV(B&R)/Secy**
4. Name & address of enlisting authority: **DDA, CRB, 1st FLOOR, VIKASMINAR**
5. Name of Work: **m/o compound recharge of N/A, SWZ, Imp of main entrance gate & platform foot path, B/wall at DDA POC 'B' BK, Janak P**
6. Agreement No.: **12/EE/WD2/DDA/11-12**
7. Name & Address of Division: **EE/WD2/B2B, JANAK PURI, ND58**

Sl.	Item	
8.1	Estimated Cost/Tender amount	1000906/- 1463593/-
8.2	Stipulated date of Commencement & Completion	8-8-11 & 2-11-11
8.3	Percentage progress with date/actual date of completion	5-11-11
8.4	Gross amount of final bill/work done	1497499/-
8.5	Amount of compensation levied, if any	NO
8.6	Amount of reduced rate items, if any	NO
8.7	Did the contractor go for arbitration ?	NO
8.8	If yes, total amount claimed and amount awarded	- NA -

Renu
Signature of the contractor

PART II

(To be filled by the department)

9.0 Certified that details given by the contractor in Part - I have been verified and found to be correct/have been corrected wherever necessary.
Delay is partly /not/ fully attributable to contractor.

S. N. B. M.
Signature of Divisional/Sub Divisional Engineer

10.0 Note : After submission of Annexure VII by contractor, reporting officer shall write the Report and forward to Reviewing officer within a week's time. Reviewing officer shall then forward the report to the Enlisting authority within a week's time.

Class	I	II	III	IV ✓	V
Reporting Officer	E.E	E.E	EE	AE	AE
Reviewing Officer	S.E	S.E	SE	EE	EE

Note: The Performance Report shall be countersigned by the respective Chief Engineer also, if the cost of the Work exceeds Rs. One Crore.

ANNEXURE VII

Part - III


(Serial 1 to 7 are repeat information for proper linkage)

1. Period:
2. Name & Address of contractor: *RENU AGGARWAL, A-21/25 Janak Puri, N.D.S.P.*
3. Class, Category and Enlistment No.: *IV BRR, F4(8) 71/06/2007/IV(BRR)/SECY*
4. Name & address of enlisting authority: *CRB, DDA, 1st Floor, VIKAS MINAR*
5. Name of Work: *M/O completed scheme of NAIT SW2 SHI - Imp of main sandraw*
6. Agreement No.: *12/EE/WD2/DDA* *gold plates, first path at B-Block, Dist*
7. Name & Address of Division: *EE/WD2/DDA/B2B, Janak Puri, N.D.S.P.*

11.1	Quality of work	Outstanding/Very good/Good/ Satisfactory /Poor
11.2	Comments on capability of contractor	
11.2.1	Technical proficiency	Outstanding/Very good/Good/Satisfactory /Poor
11.2.2	Financial soundness	Outstanding/Very good/Good/Satisfactory /Poor
11.2.3	Mobilizations of adequate T&P	Outstanding/Very good/Good/Satisfactory /Poor
11.2.4	Mobilizations of man power	Outstanding/Very good/Good/Satisfactory/ Poor
11.2.5	General behavior	Outstanding/Very good/Good/Satisfactory /Poor


 Reporting Officer (Designation and Address)
ANUR CHAUHAN
ASSTT. ENGINEER-IV
W.D.-2, D.D.A.,
JANAK PURI

12.1	Quality of work	Outstanding/Very good/Good/Satisfactory/Poor
12.2	Comments on capability of contractor	
12.2.1	Technical proficiency	Outstanding/Very good/Good/Satisfactory/Poor
12.2.2	Financial soundness	Outstanding/Very good/Good/Satisfactory/Poor
12.2.3	Mobilizations of adequate T&P	Outstanding/Very good/Good/Satisfactory/Poor
12.2.4	Mobilizations of man power	Outstanding/Very good/Good/Satisfactory/Poor
12.2.5	General behaviour	Outstanding/Very good/Good/Satisfactory/Poor


 Reviewing Officer (Designation & Address)
EE/WD-2
DDA