

ANNEXURE VII  
PERFORMANCE REPORT OF WORKS

PART I

(To be filled in by the contractor in duplicate in respect of each work cost of which falls within the range prescribed for eligibility as per para 19 of enlistment read with Table -I. One copy be submitted to Reporting Officer and other, containing acknowledgement of receipt and seal of office of reporting officer, be submitted to Secretary (CRB))

- 1. Period: 2011-2012
- 2. Name & Address of contractor: M/s Devendra Kumar Sharma, B-33 Gali No. 4 Mandawali Delhi-92
- 3. Class, Category and Enlistment No.: IV (C)
- 4. Name & address of enlisting authority: DDA
- 5. Name of Work: M/o Varanasi Scheme Under N/AJ E2, SH - Raising of B/W along Daryi Stn Distt Parle Santa Vihar
- 6. Agreement No.: 12/EE/ED-4/DDA/2011-12
- 7. Name & Address of Division: ED-4, DDA

Sl.	Item	
8.1	Estimated Cost/Tender amount	EC Rs 14,02,343/- T.A 81973999/-
8.2	Stipulated date of Commencement & Completion	5.06.2011 Doc-04.08.2011
8.3	Percentage progress with date/actual date of completion	04.08.2011
8.4	Gross amount of final bill/work done	Rs 22,72,504/-
8.5	Amount of compensation levied, if any	-
8.6	Amount of reduced rate items, if any	-
8.7	Did the contractor go for arbitration ?	-
8.8	If yes, total amount claimed and amount awarded	-

*Devendra Kumar*  
Signature of the contractor

PART II

(To be filled by the department)

9.0 Certified that details given by the contractor in Part - I have been verified and found to be correct/have been corrected wherever necessary.  
Delay is partly /not/ fully attributable to contractor.

Signature of Divisional/Sub Divisional Engineer

10.0 Note : After submission of Annexure VII by contractor, reporting officer shall write the Report and forward to Reviewing officer within a week's time. Reviewing officer shall then forward the report to the Enlisting authority within a week's time.

Class	I	II	III	IV	V
Reporting Officer	E.E	E.E	EE	AE	AE
Reviewing Officer	S.E	S.E	SE	EE	EE

Note: The Performance Report shall be countersigned by the respective Chief Engineer also, if the cost of the Work exceeds Rs. One Crore.

ANNEXURE VII  
Part -- III

(Serial I to 7 are repeat information for proper linkage)

- 1. Period: 2011-2012
- 2. Name & Address of contractor: M/s Devender Kumar Sharma, B-3 G.No 04 Mandawali Delhi 92
- 3. Class, Category and Enlistment No.: II (C)
- 4. Name & address of enlisting authority: DDA Vikas Minar New Delhi
- 5. Name of Work : M/o Vansh Scheme under N.A-II.EZ, SH: Repairing Blw along Dairy side Distt park Sarita Vihar
- 6. Agreement No. : 12/EE/ED-4/DDA/2011-2012
- 7. Name & Address of Division: ED-4 DDA

11.1	Quality of work	Outstanding/Very good/Good/ Satisfactory /Poor
11.2	Comments on capability of contractor	
11.2.1	Technical proficiency	Outstanding/Very good/Good/Satisfactory /Poor
11.2.2	Financial soundness	Outstanding/Very good/Good/Satisfactory /Poor
11.2.3	Mobilizations of adequate T&P	Outstanding/Very good/Good/Satisfactory /Poor
11.2.4	Mobilizations of man power	Outstanding/Very good/Good/Satisfactory/ Poor
11.2.5	General behavior	Outstanding/Very good/Good/Satisfactory /Poor

AE-2/ED4

Reporting Officer (Designation and Address)  
Executive Engineer  
ED4/DDA

12.1	Quality of work	Outstanding/Very good/Good/Satisfactory/Poor
12.2	Comments on capability of contractor	
12.2.1	Technical proficiency	Outstanding/Very good/Good/Satisfactory/Poor
12.2.2	Financial soundness	Outstanding/Very good/Good/Satisfactory/Poor
12.2.3	Mobilizations of adequate T&P	Outstanding/Very good/Good/Satisfactory/Poor
12.2.4	Mobilizations of man power	Outstanding/Very good/Good/Satisfactory/Poor
12.2.5	General behaviour	Outstanding/Very good/Good/Satisfactory/Poor

अभिजाती अभियन्ता  
पूर्व खण्ड IV डी.डी.पू.  
Reviewing Officer (Designation & Address)