

OFFICE OF THE EXECUTIVE ENGINEER  
WD-10/D.D.A./DWARKA/N.D.75

34

NO: F.15(7) WD-10/2011 DDA/340

Dt: 14/3/2011

To,

The Secy. (C.R.B.),  
DDA, 1st Floor,  
Vikas Minar,  
New Delhi.

Secretary (CRB)  
2-9-6  
1-6-3-4

Sub: Enlistment of contractors as class-V in DDA.  
Ref: F4(8)68/0202011/V(civil)sect./217 dt.07.3.2011.

Please find enclosed herewith the Performance  
report of contractor in respect of Sh.A.M.Constrn.Co.

Encl: Annex. IV.

*P. K. Gupta*  
EXECUTIVE ENGINEER  
WD-10/ DDA.  
P.K. Gupta (Sh P.K. Gupta)  
A.E.I.

~~A2/CR 3 2~~  
14/3

ANNEXURE - IV

CLIENT'S CERTIFICATE REG. PERFORMANCE OF CONTRACTOR

Name & Address of the Client

M/S A.M. CONSTRUCTION Co. - C-135 Part 3 DDA FLAT BINDAPUR

Details of Works executed by Shri / M/s

M/S A.M. CONSTRUCTION Co. / M/O Completed scheme under WD-10.  
384 S.F. HOUSES IN SECTOR-3 Part 1 & 2 DWARKA.

FILLING OF GROOVE IN EXISTING GRIT WASH AT OUTER FACIA OF WALL.

1.	Name of work with brief particulars	M/O COMPLETED SCHEME UNDER WD-10. 384 S.F. HOUSES IN SECTOR-3 Part 1 & 2 DWARKA. FILLING OF GROOVE IN EXISTING GRIT WASH AT OUTER FACIA OF WALL.
2.	Agreement No. and date	02/EE/WD-10/10-11/DDA
3.	Agreement amount	Rs 4,49,731/-
4.	Date of commencement of work	29.6.2010
5.	Stipulated date of completion	12.8.2010
6.	Actual date of completion	10.8.2010
7.	Details of compensation levied for delay (indicate amount) if any	- NO -
8.	Gross amount of the work completed and paid	Rs 4,49,092/-
9.	Name and address of the authority under whom works executed	EE / WD-10 / DDA Central Nursery Dwarka Sect. 3
10.	Whether the contractor employed qualified Engineer / Overseer during execution of work?	- NO -
11.	i) Quality of work (indicate grading) ii) Amt. of work paid on reduced rates, if any.	Outstanding / Very Good / Good / Satisfactory / Poor - NO -
12.	i) Did the contractor go for arbitration? ii) If yes, total amount of claim iii) Total amount awarded	- NO - - N.A -

7



Name & Address of the Client: M/S A.M. CONSTRUCTION Co. C-135 Pkt-3 DDA FLAT BINDA HOUSING

Details of Works executed by Shri / M/s A.M. Construction Co.  
M/o Completed scheme under W.D-10  
384 S.F.S. HOUSES IN SECTOR-3 Pkt 1&2 DWARKA

FILLING OF GROOVE IN EXISTING GRIT WASH AT OUTER FACIA OF WALL.

13.	Comments on the capabilities of the contractor.	
	a) Technical proficiency	Outstanding / Very Good / Good / Satisfactory / Poor ✓
	b) Financial soundness	Outstanding / Very Good / Good / Satisfactory / Poor ✓
	c) Mobilization of adequate T&P	Outstanding / Very Good / Good / Satisfactory / Poor ✓
	d) Mobilization of manpower	Outstanding / Very Good / Good / Satisfactory / Poor ✓
	e) General behavior	Outstanding / Very Good / Good / Satisfactory / Poor ✓

Note : All columns should be filled in properly "Countersigned"

*[Handwritten Signature]*  
11/3/11

Officer of the rank of Superintending Engineer or equivalent

Signature of the Reporting Officer with Office Seal

*[Handwritten Signature]*  
अधिसारी अभियन्ता  
पश्चिमी खण्ड - 10  
दि. वि. प्रा. 11/3/11  
AE-I/WD-10

अधिसारी अभियन्ता  
पश्चिमी खण्ड - 10  
दि. वि. प्रा.