

106

ANNEXURE VII
PERFORMANCE REPORT OF WORKS

PART I

(To be filled in by the contractor in duplicate in respect of each work cost of which falls within the range prescribed for eligibility as per para 19 of enlistment read with Table -I. One copy be submitted to Reporting Officer and other, containing acknowledgement of receipt and seal of office of reporting officer, be submitted to Secretary (CRB))

- 1. Period:
- 2. Name & Address of contractor: SUKHWANT SINGH, 358, Gauram Nagar, New Delhi-40
- 3. Class, Category and Enlistment No.: V (B&R) F-4 (B) 72/misc./Pt. 10/v secy/CRB/R/22
- 4. Name & address of enlisting authority: CRB, Vikas Minar, I.T.O. New Delhi
- 5. Name of Work: D/O Green area near vijay mandal Begun Pur (Area between Sarvodaya Encl. and Begun Pur) JVC/O Site Office 2 km from Begun Pur.
- 6. Agreement No.: 621 EE/SW-5/120105-01
- 7. Name & Address of Division: SWD-5, DDA, Sector 14, Vikas Minar, New Delhi.

Sl.	Item		
8.1	Estimated Cost/Tender amount	4,08,147.00	4,24,332.00
8.2	Stipulated date of Commencement & Completion		17-12-05/16-03-08
8.3	Percentage progress with date/actual date of completion		15-11-06
8.4	Gross amount of final bill/work done		Rs 4,20,821.00
8.5	Amount of compensation levied, if any		-N.A.
8.6	Amount of reduced rate items, if any		-N.A.
8.7	Did the contractor go for arbitration?		-N.A.
8.8	If yes, total amount claimed and amount awarded		-N.A.

[Signature]
Signature of the contractor

PART II

(To be filled by the department)

9.0 Certified that details given by the contractor in Part - I have been verified and found to be correct/have been corrected wherever necessary.
Delay is partly /not/ fully attributable to contractor.

[Signature]
Signature of Divisional/Sub Divisional Engineer
S.D.S, DDA

10.0 Note : After submission of Annexure VII by contractor, reporting officer shall write the Report and forward to Reviewing officer within a week's time. Reviewing officer shall then forward the report to the Enlisting authority within a week's time.

Class	I	II	III	IV	V
Reporting Officer	E.E	E.E	EE	AE	AE
Reviewing Officer	S.E	S.E	SE	EE	EE

Note: The Performance Report shall be countersigned by the respective Chief Engineer also, if the cost of the Work exceeds Rs. One Crore.

ANNEXURE VII
Part - III

(Serial 1 to 7 are repeat information for proper linkage)

1. Period:
2. Name & Address of contractor: Sukhwant Singh, 358, Rantam Nagar, New Delhi-49
3. Class, Category and Enlistment No.: V (CBDR) vide F.4 (8) 72/misc./Pt. IV/V/Secy/CRB/0/22
4. Name & address of enlisting authority: CRB, Vikas Minar
5. Name of Work : D/O Green area near vijay mandal Begun Pin (Area between Sarvodaya Encl. Baga-en. SH:- 40 Site Office & Store for Nursery)
6. Agreement No.: 62/EE/SWA-5/05-06
7. Name & Address of Division: SWD-5/DDA, Saket Vihar / New Delhi

11.1	Quality of work	Outstanding/Very good/Good/ Satisfactory /Poor
11.2	Comments on capability of contractor	
11.2.1	Technical proficiency	Outstanding/Very good/Good/Satisfactory /Poor
11.2.2	Financial soundness	Outstanding/Very good/Good/Satisfactory /Poor
11.2.3	Mobilizations of adequate T&P	Outstanding/Very good/Good/Satisfactory /Poor
11.2.4	Mobilizations of man power	Outstanding/Very good/Good/Satisfactory/ Poor
11.2.5	General behavior	Outstanding/Very good/Good/Satisfactory /Poor

Reporting Officer (Designation & Address)-VI
S.W.D.-5, DDA

12.1	Quality of work	Outstanding/Very good/Good/Satisfactory/Poor
12.2	Comments on capability of contractor	
12.2.1	Technical proficiency	Outstanding/Very good/Good/Satisfactory/Poor
12.2.2	Financial soundness	Outstanding/Very good/Good/Satisfactory/Poor
12.2.3	Mobilizations of adequate T&P	Outstanding/Very good/Good/Satisfactory/Poor
12.2.4	Mobilizations of man power	Outstanding/Very good/Good/Satisfactory/Poor
12.2.5	General behaviour	Outstanding/Very good/Good/Satisfactory/Poor

Executive Engineer
Delhi Development Authority
21.7.11
21.7.11

ANNEXURE VII
PERFORMANCE REPORT OF WORKS

PART I

(To be filled in by the contractor in duplicate in respect of each work cost of which falls within the range prescribed for eligibility as per para 19 of enlistment read with Table -I. One copy be submitted to Reporting Officer and other, containing acknowledgement of receipt and seal of office of reporting officer, be submitted to Secretary (CRB))

- 1. Period: 2005-06
- 2. Name & Address of contractor: Sukhrewal-Singh, 358 Gauram Nagar, New Delhi-110048.
- 3. Class, Category and Enlistment No.: V (CRB) (Fu (8) 72 mise/rr IV/v/see/CRB)
- 4. Name & address of enlisting authority: CRB, Vihar, New Delhi
- 5. Name of Work: P.U. green area near Vijeey Memorial Begampur (Area between Sarvodaya Enclave & Begampur)
- 6. Agreement No.: 62/SE/MDJ/POA/05-06
- 7. Name & Address of Division: SE/SMDJ/POA, Sanita Vihar, New Delhi-110167

Sl.	Item	
8.1	Estimated Cost/Tender amount	Rs. 4,08,147/- & Rs. 424322/-
8.2	Stipulated date of Commencement & Completion	17.12.05 & 16.3.06
8.3	Percentage progress with date/actual date of completion	15.11.06.
8.4	Gross amount of final bill/work done	Rs. 4,20,821/-
8.5	Amount of compensation levied, if any	- NO -
8.6	Amount of reduced rate items, if any	- Nil -
8.7	Did the contractor go for arbitration ?	- NO -
8.8	If yes, total amount claimed and amount awarded	- N.A. -

[Signature]
Signature of the contractor

PART II

(To be filled by the department)

9.0 Certified that details given by the contractor in Part - I have been verified and found to be correct/have been corrected wherever necessary.
Delay is partly /not/ fully attributable to contractor.

[Signature]
Signature of Divisional/Sub-Divisional Engineer

10.0 Note : After submission of Annexure VII by contractor reporting officer shall write the Report and forward to Reviewing officer within a week's time. Reviewing officer shall then forward the report to the Enlisting authority within a week's time.

Class	I	II	III	IV	V
Reporting Officer	E.E	E.E	EE	AE	AE
Reviewing Officer	S.E	S.E	SE	EE	EE

Note: The Performance Report shall be countersigned by the respective Chief Engineer also, if the cost of the Work exceeds Rs. One Crore.

ANNEXURE VII
Part - III

(Serial 1 to 7 are repeat information for proper linkage)

- 1. Period: 2005-06.
- 2. Name & Address of contractor: Sulekh weel Sugh, 358 Gauram Nagar, New Delhi - 110049.
- 3. Class, Category and Enlistment No.: I (B) vide #4(8) 724 mize [BH I / V / sec 1]
- 4. Name & address of enlisting authority: CRB, Vikas Minar
- 5. Name of Work: D/o green area, near Vijay Mandir Begunpur (Area between Sanyodhya Enclave & Begunpur).
- 6. Agreement No.: SN-40 site office & store for Nursery.
- 7. Name & Address of Division: Ex. Engineer / SWPS / DDA, Convent Vikas, New Delhi

11.1	Quality of work	Outstanding/Very good/Good/ Satisfactory /Poor
11.2	Comments on capability of contractor	
11.2.1	Technical proficiency	Outstanding/Very good/Good/Satisfactory /Poor
11.2.2	Financial soundness	Outstanding/Very good/Good/Satisfactory /Poor
11.2.3	Mobilizations of adequate T&P	Outstanding/Very good/Good/Satisfactory /Poor
11.2.4	Mobilizations of man power	Outstanding/Very good/Good/Satisfactory/ Poor
11.2.5	General behavior	Outstanding/Very good/Good/Satisfactory /Poor

[Signature]
18/8/11
Asstt. Engineer
Reporting Officer (Designation and Address)
Delhi Development Authority

12.1	Quality of work	Outstanding/Very good/Good/Satisfactory/Poor
12.2	Comments on capability of contractor	
12.2.1	Technical proficiency	Outstanding/Very good/Good/Satisfactory/Poor
12.2.2	Financial soundness	Outstanding/Very good/Good/Satisfactory/Poor
12.2.3	Mobilizations of adequate T&P	Outstanding/Very good/Good/Satisfactory/Poor
12.2.4	Mobilizations of man power	Outstanding/Very good/Good/Satisfactory/Poor
12.2.5	General behaviour	Outstanding/Very good/Good/Satisfactory/Poor

[Signature]
Executive Engineer
Reviewing Officer (Designation & Address)
Delhi Development Authority